


# Flood Resulting from Xe Namnoy Xe Pian Dam Collapse in Lao PDR




## Legend

- Surface water on 25 July 2018
- Affected villages
- Village
- Health facilities
- Schools
- Primary road
- Secondary road

## Description:

The map shows the water inundation areas caused by the collapsed dam, and flooded villages downstream the location of the dam (which 5 of them shown in RED have been confirmed by the relevant agency in Laos).

This map depicts the situation as of 25 July 2018 and will be updated whenever the newer data and information become available



Source :  
 - Satellite data provider : JAXA  
 ALOS/PALSAR 25 July 2018, 16:23 UTC  
 Baseline data :  
 - National Risk Profile of Lao PDR, UNDP Laos, 2010

Acknowledgement:  
 Additional processing and analysis conducted by  
 Asian Disaster Preparedness Center, ADPC