
## Mapping Inundation extent of dam break in Attapau province (Lao PDR) using ALOS 2 PALSAR 2 Satellite Data (25 July 2018)





The analysis excluded permanent water bodies including reservoir, tanks and ponds and this reflects only the inundation extent. Please note the surface water extent mapped has not yet been validated in

The depiction and use of boundaries, geographic