



Receding of water from the reservoir

Flooded area (red) due to dam break

Satellite Image : Sentinel-1
Pre - 17 July 2018
Post - 25 July 2018

